

N:/DGN/CLIENTS/CLPINE/172012/BKRHALF.DGN

Air Insulated Substation -- Breaker & One Half - East / West

Metcalf Energy Center

Figure 5.2-2

Prepared by
Commonwealth Associates Inc.
Jackson, Michigan
engineers consultants construction managers

3/16/99



N:\DGN\CLIENTS\CLPINE\ 172012\CBLTERM2

Typical 230 kV Cable Termination Inside Substation

Metcalf Energy Center

Figure 5.2-7

Prepared by
Commonwealth Associates Inc.
Jackson, Michigan
engineers consultants construction managers

3/16/99



Typical 230 kV Splicing Manhole

Metcalf Energy Center

Figure 5.2-8

Prepared by
Commonwealth Associates Inc.
Jackson, Michigan
engineers consultants construction managers

3/16/99



Typical Fluid Pressurizing Station, High-Pressure Fluid-Filled Cable

Metcalf Energy Center

Figure 5.2-9

Prepared by
Commonwealth Associates Inc.
Jackson, Michigan
engineers consultants construction managers

3/16/99



Transmission Lines at PG&E Metcalf Substation

Metcalf Energy Center

Figure 5.5-1

Prepared by
Commonwealth Associates Inc.
Jackson, Michigan
engineers consultants construction managers

3/16/99



Electric Field Within Right-of-Way
PG&E Transmission Corridor Adjacent to Proposed Energy Center
Metcalf Energy Center

Figure 5.5-3

Prepared by
Commonwealth Associates Inc.
Jackson, Michigan
engineers consultants construction managers

3/16/99



Magnetic Field Within Right-of-Way
PG&E Transmission Corridor Adjacent to Proposed Energy Center
Metcalf Energy Center

Figure 5.5-4

Prepared by
Commonwealth Associates Inc.
Jackson, Michigan
engineers consultants construction managers

3/16/99